



PHOTO #7. 4125 Levick St.-Rear and side of row home-Repaired step cracks from 1st and 2nd floor windows and from corner of structure through foundation wall on both sides of building.